



DEPARTMENT OF THE ARMY

**TOBYHANNA ARMY DEPOT
11 HAP ARNOLD BOULEVARD
TOBYHANNA, PENNSYLVANIA**

18466-5086
01 MAR 2002

Environmental Management Division

Commonwealth of Pennsylvania
Department of Environmental Protection
Bureau of Land Recycling and Waste Management
Post Office Box 8550
Harrisburg, Pennsylvania 17105-8550

Dear Sir or Madam:

Enclosed is Tobyhanna Army Depot's 2001 U.S Environmental Protection Agency Hazardous Waste Report.

If there are any questions about the report, the installation point of contact for this information is Mr. Randy Didier, Chief, Environmental Management Division, at (570) 895-7090, or e-mail, randy.didier@tobyhanna.army.mil.

Sincerely,

Randy Didier
Chief, Environmental Management Division

Enclosure

MAIL THE COMPLETED FORM TO: The Appropriate EPA Regional State Office.	United States Environmental Protection Agency RCRA SUBTITLE C SITE IDENTIFICATION FORM		
1. Reason for Submittal and Status of Information Supplied (see instructions on pages 10 and 11) CHECK CORRECT BOX(ES)	A. Reason for Submittal: <input type="checkbox"/> To provide initial notification (to obtain an EPA ID Number for hazardous waste, universal waste, or used oil activities). <input type="checkbox"/> To provide subsequent notification (to update site identification information). <input type="checkbox"/> As a component of a First RCRA Hazardous Waste Part A Permit Application. <input type="checkbox"/> As a component of a Revised RCRA Hazardous Waste Part A Permit Application (Amendment # _____). <input checked="" type="checkbox"/> As a component of the Hazardous Waste Report. B. Status of Information Supplied: <input checked="" type="checkbox"/> Updated site information		
2. Site EPA ID Number (see instructions on page 11)	EPA ID Number: PA5213820892		
3 Site Name (see instructions on page 11)	Legal Name: TOBYHANNA ARMY DEPOT		
4. Site Location information (see instructions on page 11)	Street Address: 11 HAP ARNOLD BLVD		
	City, Town, or Village: TOBYHANNA	State: PA	
	County Name: MONROE	Zip Code: 18466-5086	
5. Site Land Type (see instructions on page 11)	Site Land Type: <input type="checkbox"/> Private <input type="checkbox"/> County <input type="checkbox"/> District <input checked="" type="checkbox"/> Federal <input type="checkbox"/> Indian <input type="checkbox"/> Municipality <input type="checkbox"/> State <input type="checkbox"/> Other		
6. North American Industry Classification system (NAIC) Code(s) for the Site (see instructions on page 11)	A. 928110		B.
	C.		D.
7. Site Mailing Address (see instructions on page 12)	Street or P.O. Box: SAME		
	City, Town, or Village:		
	State:		
	County Name:	Zip Code: 18466-5086	
8. Site Contact Person (see instructions on page 12)	First Name: RANDY	MI:	Last Name: DIDIER
	Phone Number: 570-895-7090		Phone Number Extension:
9. Legal Owner and Operator of the Site (see instructions on pages 12 and 13)	A. Name of Site's Legal Owner: TOBYHANNA ARMY DEPOT		Date Became Owner (mm/dd/yyyy):
	Owner Type: <input type="checkbox"/> Private <input type="checkbox"/> County <input type="checkbox"/> District <input checked="" type="checkbox"/> Federal <input type="checkbox"/> Indian <input type="checkbox"/> Municipality <input type="checkbox"/> State <input type="checkbox"/> Other		
	B. Name of Site's Operator: SAME		Date Became Operator (mm/dd/yyyy):
	Operator Type: <input type="checkbox"/> Private <input type="checkbox"/> County <input type="checkbox"/> District <input checked="" type="checkbox"/> Federal <input type="checkbox"/> Indian <input type="checkbox"/> Municipality <input type="checkbox"/> State <input type="checkbox"/> Other		

10. Type of regulated Waste Activity (Mark 'X' in the appropriate boxes. See instructions on pages 13, 14, 15 and 16)**A. Hazardous Waste Activities****1. Generator of hazardous Waste**

- ☒ a. LQG: Greater than 1,000 kg/mo (2,200 lbs.) of non-acute hazardous waste; or
- ☐ b. SQG: 100 to 1,000 kg/mo (220 - 2,200 lbs.) of non-acute hazardous waste; or
- ☐ c. CESQG: Less than 100 kg/mo of non-acute hazardous waste

In addition, indicate other generator activities (check all that apply)

- ☐ d. United States Importer of Hazardous Waste
- ☐ e. Mixed Waste (hazardous and radioactive) Generator

For Items 2 through 6, check all that apply:

- ☐ 2. Transporter of Hazardous Waste
- ☒ 3. Treater, Storer, or Disposer of Hazardous Waste (at your site) Note: A hazardous waste permit is required for this activity.
- ☐ 4. Recycler of Hazardous Waste (at your site) Note: A hazardous waste permit is required for this activity.
5. Exempt Boiler and/or Industrial Furnace
- ☐ a. Small Quantity On-site Burner Exemption
- ☐ b. Smelting, Melting, Refining Furnace Exemption
- ☐ 6. Underground Injection Control

B. Universal Waste Activities

1. Large Quantity Handler of Universal Waste [refer to your State regulations to determine what is regulated]. Indicate types of universal waste generated and/or accumulated at your site. (check all boxes that apply):

	<u>Generated</u>	<u>Accumulated</u>
a. Batteries	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
b. Pesticides	<input type="checkbox"/>	<input type="checkbox"/>
c. Thermostats	<input type="checkbox"/>	<input type="checkbox"/>
d. Lamps	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
e. Other (specify)	<input type="checkbox"/>	<input type="checkbox"/>
f. Other (specify)	<input type="checkbox"/>	<input type="checkbox"/>
g. Other (specify)	<input type="checkbox"/>	<input type="checkbox"/>

☐ 2. Destination Facility for Universal Waste

Note: A hazardous waste permit is required for this activity.

C. Used Oil Activities**1. Used Oil Transporter - Indicate Type(s) of Activity(ies)**

- ☐ a. Transporter
- ☐ b. Transfer Facility

2. Used Oil Processor and/or Re-refiner - Indicate Type(s)

- ☐ a. Processor
- ☐ b. Re-refiner

☐ 3. Off-Specification Used Oil Burner**4. Used Oil Fuel Marketer - Indicate Type(s) of Activity(ies)**

- ☐ a. Marketer Who Directs Shipment of Off-Specification
- ☐ b. Marketer Who First Claims the Used Oil Meets the Specifications

11. Description of Hazardous Wastes (see instructions on page 16)

A. Waste Codes for Federally Regulated Hazardous Wastes. Please list the waste codes of the Federal hazardous wastes handled at your site. List them in the order they are presented in the regulations (e.g., D001, D003, F007, U112). Use an additional page if more spaces are needed.


D001 D002 D003 D004 D006 D007 D008 D009 D010 D011 D018 D019 D028 D029 D035 D039 D040 D043 F002 F003 F005 F006 U080 U226 U239

EPA ID No. PA5213820892

B. Waste Codes for State Regulated Hazardous Wastes. Please list the waste codes of the State-regulated hazardous wastes handled at your site. List them in the order they are presented in the regulations. Use an additional page if more spaces are needed for waste codes.

12. Comments (see instructions on page 17)

13. Certification. I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations. (see instructions on page 17)

Signature of owner, operator, or an authorized representative	Name and Official Title (type or print)	Date Signed (mm-dd-yyyy)
	RANDY DIDIER, Chief, Environmental Management Div	28 Feb 02

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) SANDBLAST GRIT				
B. EPA hazardous waste code (page 22)		<u>D006</u>	<u>D007</u>	C. State hazardous waste code (page 22)	
<u>NA</u>		<u>NA</u>	<u>NA</u>	<u>NA</u>	
D. Source Code (page 23)	<u>G06</u>	E. Form code (page 23)	<u>W519</u>	F. RCRA radioactive mixed (page 23)	<input checked="" type="checkbox"/> No
Management Method code for Source code G25				G. Quantity generated in 2001 (page 23)	<u>215</u>
				H. UOM (page 15) Density	<u>LBS</u> <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg

Sec. 2	Was any of this waste managed on site? (page 24)	
[] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)		
[X] No (SKIP TO SEC 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24)
		Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H131</u>	D. Total quantity shipped in 2001 (page 26) <u>215</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) MERCURY SPILL				
B. EPA hazardous waste code (page 22) <u>NA</u> <u>NA</u> <u>NA</u>			C. State hazardous waste code (page 22) <u>NA</u> <u>NA</u>		
D. Source Code (page 23) <u>G32</u> Management Method code for Source code G25		E. Form code (page 23) <u>W117</u>	F. RCRA radioactive mixed (page 23) <input checked="" type="checkbox"/> No	G. Quantity generated in 2001 (page 23) <u>5</u>	H. UOM (page 15) Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg <u>LBS</u>

Sec. 2	Was any of this waste managed on site? (page 24) <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)		On-site Management Method code (page 24)
Quantity treated, disposed, or recycled on site in 2001 (page 25)		Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26) <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H131</u>	D. Total quantity shipped in 2001 (page 26) <u>5</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u> </u>	D. Total quantity shipped in 2001 (page 26) <u> </u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u> </u>	D. Total quantity shipped in 2001 (page 26) <u> </u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

2001 Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) <u>X-RAY DEVELOPER</u>				
B. EPA hazardous waste code (page 22)		<u>D004</u>	<u>NA</u>	C. State hazardous waste code (page 22)	
<u>NA</u>		<u>NA</u>	<u>NA</u>	<u>NA</u> <u>NA</u>	
D. Source Code (page 23)		<u>G09</u>	E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)
Management Method code for Source code G25			<u>W219</u>	<u>[X] No</u>	<u>247</u>
					H. UOM (page 15) <u>LBS</u> Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg.

Sec. 2	Was any of this waste managed on site? (page 24)	
	[] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)	
	[X] No (SKIP TO SEC 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
	<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H077</u>	D. Total quantity shipped in 2001 (page 26) <u>229</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1					
A. Waste description (page 22) <u>FIXER SOLUTION</u>					
B. EPA hazardous waste code (page 22)		C. State hazardous waste code (page 22)			
<u>D004</u> <u>D011</u>		<u>D010</u> <u>NA</u>		<u>NA</u> <u>NA</u>	
D. Source Code (page 23) <u>G19</u> Management Method code for Source code G25		E. Form code (page 23) <u>W219</u>		F. RCRA radioactive mixed (page 23) <input checked="" type="checkbox"/> No	
		G. Quantity generated in 2001 (page 23) <u>397</u>		H. UOM (page 15) Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	

Sec. 2	
Was any of this waste managed on site? (page 24) <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC 3)	
ON-SITE PROCESS SYSTEM 1	
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)
ON-SITE PROCESS SYSTEM 2	
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3			
A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26) <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H129</u>	D. Total quantity shipped in 2001 (page 26) <u>390</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

2001 Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) <u>ETCH SOLUTION</u>				
B. EPA hazardous waste code (page 22)		<u>D001</u>	<u>D002</u>	C. State hazardous waste code (page 22)	
<u>D018</u>		<u>D019</u>	<u>D028</u>	<u>NA</u> <u>NA</u>	
D. Source Code (page 23)	<u>G04</u>	E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)	H. UOM (page 15) <u>LBS</u>
Management Method code for Source code G25		<u>W110</u>	<u>[X]</u> No	<u>76</u>	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg

Sec. 2	Was any of this waste managed on site? (page 24)	
<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H129</u>	D. Total quantity shipped in 2001 (page 26) <u>76</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u> </u>	D. Total quantity shipped in 2001 (page 26) <u> </u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u> </u>	D. Total quantity shipped in 2001 (page 26) <u> </u>

Comments:
Sec. I, Box B, continued: D029, D039, D043

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1		A. Waste description (page 22) AEROSOL WASTE			
B. EPA hazardous waste code (page 22)		<u>D001</u>	<u>D035</u>	C. State hazardous waste code (page 22)	
<u>D040</u>		<u>F002</u>	<u>F005</u>	<u>NA</u> <u>NA</u>	
D. Source Code (page 23)		E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)	H. UOM (page 15) Density
<u>G11</u> Management Method code for Source code G25		<u>W203</u>	<input checked="" type="checkbox"/> No	<u>251</u>	<u>LBS</u> <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg

Sec. 2	Was any of this waste managed on site? (page 24)	
	<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)		On-site Management Method code (page 24)
Quantity treated, disposed, or recycled on site in 2001 (page 25)		Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
	<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>IND000646943</u>	<u>H040</u>	<u>149</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>NA</u>		
Site 3	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>NA</u>		

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) PAINT IN CANS				
B. EPA hazardous waste code (page 22)		C. State hazardous waste code (page 22)			
<u>NA</u> <u>D001</u> <u>NA</u>		<u>NA</u> <u>NA</u>			
D. Source Code (page 23) <u>G06</u> Management Method code for Source code G25		E. Form code (page 23) <u>W209</u>	F. RCRA radioactive mixed (page 23) <input checked="" type="checkbox"/> No	G. Quantity generated in 2001 (page 23) <u>525</u>	H. UOM (page 15) Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg <u>LBS</u>

Sec. 2	Was any of this waste managed on site? (page 24) <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)		On-site Management Method code (page 24)
Quantity treated, disposed, or recycled on site in 2001 (page 25)		Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26) <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H040</u>	D. Total quantity shipped in 2001 (page 26) <u>525</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

2001 Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) <u>PAINT</u>				
B. EPA hazardous waste code (page 22)		<u>D001</u>	<u>D035</u>	C. State hazardous waste code (page 22)	
<u>F003</u>		<u>F005</u>	<u>NA</u>	<u>NA</u> <u>NA</u>	
D. Source Code (page 23)		E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)	H. UOM (page 15) Density
<u>G06</u> Management Method code for Source code G25		<u>W209</u>	<input checked="" type="checkbox"/> No	<u>40991</u>	<u>LBS</u> <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg

Sec. 2	Was any of this waste managed on site? (page 24)	
<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H040</u>	D. Total quantity shipped in 2001 (page 26) <u>34717</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u>NA</u>	D. Total quantity shipped in 2001 (page 26) <u>NA</u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u>NA</u>	D. Total quantity shipped in 2001 (page 26) <u>NA</u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) <u>THINNER RAGS</u>				
B. EPA hazardous waste code (page 22)		<u>D001</u>	<u>D035</u>	C. State hazardous waste code (page 22)	
<u>F003</u>		<u>F005</u>	<u>NA</u>	<u>NA</u> <u>NA</u>	
D. Source Code (page 23)	<u>G06</u>	E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)	H. UOM (page 15) <u>LBS</u> Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
Management Method code for Source code G25		<u>W409</u>	<input checked="" type="checkbox"/> No	<u>3984</u>	

Sec. 2	Was any of this waste managed on site? (page 24)	
<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H040</u>	D. Total quantity shipped in 2001 (page 26) <u>3218</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u>NA</u>	D. Total quantity shipped in 2001 (page 26) <u>NA</u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u>NA</u>	D. Total quantity shipped in 2001 (page 26) <u>NA</u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

2001 Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1 A. Waste description (page 22)
SODIUM PERSULFATE

B. EPA hazardous waste code (page 22) D001 D002
NA NA NA

C. State hazardous waste code (page 22)
NA NA

D. Source Code (page 23) G06
Management Method code for
Source code G25

E. Form code (page 23)
W105

F. RCRA radioactive mixed (page 23)
☒ No

G. Quantity generated in 2001 (page 23)
823

H. UOM (page 15) LBS
Density
☐ 1 lbs/gal ☐ 2 sg

Sec. 2 Was any of this waste managed on site? (page 24)
☐ Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)
☒ No (SKIP TO SEC 3)

ON-SITE PROCESS SYSTEM 1

On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

ON-SITE PROCESS SYSTEM 2

On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3 A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)
☒ 1 Yes (CONTINUE TO BOX B) ☐ 2 No (FORM IS COMPLETE)

Site 1 B. EPA ID No. of facility waste was shipped (page 26)
IND000646943

C. Off-site Management Method code Shipped to (page 26)
H121

D. Total quantity shipped in 2001 (page 26)
330

Site 2 B. EPA ID No. of facility waste was shipped (page 26)
NA

C. Off-site Management Method code Shipped to (page 26)

D. Total quantity shipped in 2001 (page 26)

Site 3 B. EPA ID No. of facility waste was shipped (page 26)
NA

C. Off-site Management Method code Shipped to (page 26)

D. Total quantity shipped in 2001 (page 26)

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) ACCELERATOR 19				
B. EPA hazardous waste code (page 22)		<u>D002</u>	<u>NA</u>	C. State hazardous waste code (page 22)	
<u>NA</u>		<u>NA</u>	<u>NA</u>	<u>NA</u> <u>NA</u>	
D. Source Code (page 23)	<u>G03</u>	E. Form code (page 23)	<u>W105</u>	F. RCRA radioactive mixed (page 23)	[X] No
Management Method code for Source code G25				G. Quantity generated in 2001 (page 23)	<u>874</u>
				H. UOM (page 15)	<u>LBS</u>
				Density	<input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg

Sec. 2	Was any of this waste managed on site? (page 24)	
	[] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)	
	[X] No (SKIP TO SEC 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24)
		Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
	<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H121</u>	D. Total quantity shipped in 2001 (page 26) <u>467</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

2001 Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1 A. Waste description (page 22)
CATALYST 9F - HYDROCHLORIC ACID

B. EPA hazardous waste code (page 22) D002 D008
NA NA NA

C. State hazardous waste code (page 22)
NA NA

D. Source Code (page 23) G06
Management Method code for
Source code G25

E. Form code (page 23)
W105

F. RCRA radioactive mixed (page 23)
☒ No

G. Quantity generated in 2001 (page 23)
1114

H. UOM (page 15) LBS
Density
☐ 1 lbs/gal ☐ 2 sg

Sec. 2 Was any of this waste managed on site? (page 24)
☐ Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)
☒ No (SKIP TO SEC 3)

ON-SITE PROCESS SYSTEM 1

On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

ON-SITE PROCESS SYSTEM 2

On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3 A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)
☒ 1 Yes (CONTINUE TO BOX B) ☐ 2 No (FORM IS COMPLETE)

Site 1 B. EPA ID No. of facility waste was shipped (page 26)
IND000646943

C. Off-site Management Method code Shipped to (page 26)
H077

D. Total quantity shipped in 2001 (page 26)
624

Site 2 B. EPA ID No. of facility waste was shipped (page 26)
NA

C. Off-site Management Method code Shipped to (page 26)

D. Total quantity shipped in 2001 (page 26)

Site 3 B. EPA ID No. of facility waste was shipped (page 26)
NA

C. Off-site Management Method code Shipped to (page 26)

D. Total quantity shipped in 2001 (page 26)

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) <u>ULTRA ETCH FINE LINE</u>				
B. EPA hazardous waste code (page 22)		<u>D002</u>	<u>D004</u>	C. State hazardous waste code (page 22)	
<u>NA</u>		<u>NA</u>	<u>NA</u>	<u>NA</u> <u>NA</u>	
D. Source Code (page 23)	<u>G04</u>	E. Form code (page 23)	<u>W110</u>	F. RCRA radioactive mixed (page 23)	[X] No
Management Method code for Source code G25				G. Quantity generated in 2001 (page 23)	<u>2177</u>
				H. UOM (page 15)	<u>LBS</u>
				Density	<input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg

Sec. 2	Was any of this waste managed on site? (page 24)	
[] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)		
[X] No (SKIP TO SEC 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24)
		Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H077</u>	D. Total quantity shipped in 2001 (page 26) <u>2177</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) FLUORBORIC COPPER SOLUTION				
B. EPA hazardous waste code (page 22)		<u>D002</u>	<u>D004</u>	C. State hazardous waste code (page 22)	
<u>D007</u>		<u>D008</u>	<u>NA</u>	<u>NA</u> <u>NA</u>	
D. Source Code (page 23)		E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)	H. UOM (page 15) Density
<u>G03</u> Management Method code for Source code G25		<u>W103</u>	[X] No	<u>4835</u>	<u>LBS</u> <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg.

Sec. 2	Was any of this waste managed on site? (page 24)	
[] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)		
[X] No (SKIP TO SEC 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>IND000646943</u>	<u>H077</u>	<u>609</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>NA</u>		
Site 3	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>NA</u>		

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) ELECTROLESS COPPER SOLUTION				
B. EPA hazardous waste code (page 22)		C. State hazardous waste code (page 22)			
<u>NA</u> <u>D002</u> <u>NA</u>		<u>NA</u> <u>NA</u>			
D. Source Code (page 23)		E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)	H. UOM (page 15) Density
<u>G03</u> Management Method code for Source code G25		<u>W110</u>	<u>[X] No</u>	<u>2445</u>	<u>LBS</u> <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg

Sec. 2	Was any of this waste managed on site? (page 24)	
	[] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)	
	[X] No (SKIP TO SEC 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
	<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>IND000646943</u>	<u>H121</u>	<u>1309</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>NA</u>		
Site 3	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>NA</u>		

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) WASTE SULFIDE SLUDGE				
B. EPA hazardous waste code (page 22)		C. State hazardous waste code (page 22)			
<u>NA</u> <u>NA</u> <u>NA</u>		<u>NA</u> <u>NA</u>			
D. Source Code (page 23) <u>G23</u> Management Method code for Source code G25		E. Form code (page 23) <u>W504</u>	F. RCRA radioactive mixed (page 23) <input checked="" type="checkbox"/> No	G. Quantity generated in 2001 (page 23) <u>14298</u>	H. UOM (page 15) Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg

Sec. 2	Was any of this waste managed on site? (page 24) <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26) <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H131</u>	D. Total quantity shipped in 2001 (page 26) <u>13022</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u>NA</u>	D. Total quantity shipped in 2001 (page 26) <u>NA</u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u>NA</u>	D. Total quantity shipped in 2001 (page 26) <u>NA</u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) <u>STEEL DUST</u>				
B. EPA hazardous waste code (page 22)		<u>D006</u>	<u>D007</u>	C. State hazardous waste code (page 22)	
<u>NA</u>		<u>NA</u>	<u>NA</u>	<u>NA</u> <u>NA</u>	
D. Source Code (page 23)		E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)	H. UOM (page 15) <u>LBS</u> Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg.
<u>G06</u> Management Method code for Source code G25		<u>W519</u>	<input checked="" type="checkbox"/> No	<u>8149</u>	

Sec. 2	Was any of this waste managed on site? (page 24) <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26) <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H131</u>	D. Total quantity shipped in 2001 (page 26) <u>6879</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u> </u>	D. Total quantity shipped in 2001 (page 26) <u> </u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u> </u>	D. Total quantity shipped in 2001 (page 26) <u> </u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

2001 Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) PAINT DUST				
B. EPA hazardous waste code (page 22)		<u>D006</u>	<u>D007</u>	C. State hazardous waste code (page 22)	
<u>NA</u>		<u>NA</u>	<u>NA</u>	<u>NA</u>	
D. Source Code (page 23) <u>G09</u> Management Method code for Source code G25		E. Form code (page 23) <u>W519</u>	F. RCRA radioactive mixed (page 23) <input checked="" type="checkbox"/> No	G. Quantity generated in 2001 (page 23) <u>3799</u>	H. UOM (page 15) Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg <u>LBS</u>

Sec. 2	Was any of this waste managed on site? (page 24) <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26) <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H131</u>	D. Total quantity shipped in 2001 (page 26) <u>3122</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u> </u>	D. Total quantity shipped in 2001 (page 26) <u> </u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u> </u>	D. Total quantity shipped in 2001 (page 26) <u> </u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) SANDBLAST GRIT				
B. EPA hazardous waste code (page 22)		<u>D006</u>	<u>D007</u>	C. State hazardous waste code (page 22)	
<u>D008</u>		<u>NA</u>	<u>NA</u>	<u>NA</u> <u>NA</u>	
D. Source Code (page 23) <u>G06</u> Management Method code for Source code G25		E. Form code (page 23) <u>W519</u>	F. RCRA radioactive mixed (page 23) [X] No	G. Quantity generated in 2001 (page 23) <u>31489</u>	H. UOM (page 15) <u>LBS</u> Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg

Sec. 2	Was any of this waste managed on site? (page 24) [] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) [X] No (SKIP TO SEC 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26) <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H131</u>	D. Total quantity shipped in 2001 (page 26) <u>26696</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u> </u>	D. Total quantity shipped in 2001 (page 26) <u> </u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u> </u>	D. Total quantity shipped in 2001 (page 26) <u> </u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

2001 Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) SANDBLAST WASTE - GLOVES, SANDPAPER, COVERALLS				
B. EPA hazardous waste code (page 22)		C. State hazardous waste code (page 22)			
<u>NA</u> <u>D006</u> <u>NA</u> <u>NA</u> <u>NA</u> <u>NA</u>		<u>NA</u> <u>NA</u>			
D. Source Code (page 23)	E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)	H. UOM (page 15) Density	
<u>G19</u> Management Method code for Source code G25	<u>W519</u>	<input checked="" type="checkbox"/> No	<u>11954</u>	<u>LBS</u> <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	

Sec. 2	Was any of this waste managed on site? (page 24)	
<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H131</u>	D. Total quantity shipped in 2001 (page 26) <u>9798</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u> </u>	D. Total quantity shipped in 2001 (page 26) <u> </u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u> </u>	D. Total quantity shipped in 2001 (page 26) <u> </u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

2001 Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) SANDBLAST GRIT FILTERS				
B. EPA hazardous waste code (page 22)		<u>D006</u>	<u>D007</u>	C. State hazardous waste code (page 22)	
<u>D008</u>		<u>NA</u>	<u>NA</u>	<u>NA</u> <u>NA</u>	
D. Source Code (page 23)	<u>G25</u>	E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)	H. UOM (page 15) Density
Management Method code for Source code G25		<u>W519</u>	<input checked="" type="checkbox"/> No	<u>7111</u>	<u>LBS</u> <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg

Sec. 2	Was any of this waste managed on site? (page 24)	
<input checked="" type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)		
<input type="checkbox"/> No (SKIP TO SEC 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)
	<u>7111</u>	

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H131</u>	D. Total quantity shipped in 2001 (page 26) <u>6211</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

2001 Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) STEAM SUMP SLUDGE				
B. EPA hazardous waste code (page 22)		C. State hazardous waste code (page 22)			
<u>NA</u> <u>NA</u> <u>NA</u>		<u>NA</u> <u>NA</u>			
D. Source Code (page 23) <u>G09</u> Management Method code for Source code G25		E. Form code (page 23) <u>W609</u>	F. RCRA radioactive mixed (page 23) <input checked="" type="checkbox"/> No	G. Quantity generated in 2001 (page 23) <u>327</u>	H. UOM (page 15) Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg <u>LBS</u>

Sec. 2	Was any of this waste managed on site? (page 24) <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26) <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H131</u>	D. Total quantity shipped in 2001 (page 26) <u>327</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u>NA</u>	D. Total quantity shipped in 2001 (page 26) <u>NA</u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u>NA</u>	D. Total quantity shipped in 2001 (page 26) <u>NA</u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

2001 Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) BATTERIES CONTAINING HIGH LEVEL MERCURY				
B. EPA hazardous waste code (page 22)		C. State hazardous waste code (page 22)			
<u>NA</u> <u>D009</u> <u>NA</u> <u>NA</u> <u>NA</u> <u>NA</u>		<u>NA</u> <u>NA</u>			
D. Source Code (page 23)	Management Method code for Source code G25	E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)	H. UOM (page 15) Density
<u>G16</u>		<u>W309</u>	<u>[X]</u> No	<u>65</u>	<u>LBS</u> <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg

Sec. 2	Was any of this waste managed on site? (page 24)	
	<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
	<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H131</u>	D. Total quantity shipped in 2001 (page 26) <u>65</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) WASTE LITHIUM BATTERIES				
B. EPA hazardous waste code (page 22)		<u>D001</u>	<u>D003</u>	C. State hazardous waste code (page 22)	
<u>NA</u>		<u>NA</u>	<u>NA</u>	<u>NA</u> <u>NA</u>	
D. Source Code (page 23)		E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)	H. UOM (page 15) Density
<u>G16</u> Management Method code for Source code G25		<u>W309</u>	<u>[X] No</u>	<u>363652</u>	<u>LBS</u> <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg.

Sec. 2	Was any of this waste managed on site? (page 24)	
<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>EXEMPT</u>	<u>H010</u>	<u>402680</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>IND000646943</u>	<u>H010</u>	<u>557</u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>NA</u>		

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) NICKEL CADMIUM BATTERIES				
	B. EPA hazardous waste code (page 22) <u>NA</u>		C. State hazardous waste code (page 22) <u>NA</u>		
D. Source Code (page 23) <u>G16</u> Management Method code for Source code G25	E. Form code (page 23) <u>W309</u>	F. RCRA radioactive mixed (page 23) [X] No	G. Quantity generated in 2001 (page 23) <u>558</u>	H. UOM (page 15) Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	
				LBS	

Sec. 2	Was any of this waste managed on site? (page 24) [] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) [X] No (SKIP TO SEC 3)	
	ON-SITE PROCESS SYSTEM 1 On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)	ON-SITE PROCESS SYSTEM 2 On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26) <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	Site 1	Site 2	Site 3
	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H131</u>	D. Total quantity shipped in 2001 (page 26) <u>466</u>
	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u> </u>	D. Total quantity shipped in 2001 (page 26) <u> </u>
	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u> </u>	D. Total quantity shipped in 2001 (page 26) <u> </u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

2001 Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) SILVER BATH SOLUTION				
B. EPA hazardous waste code (page 22)		<u>D004</u>	<u>D006</u>	C. State hazardous waste code (page 22)	
<u>D010</u>		<u>D011</u>	<u>NA</u>	<u>NA</u> <u>NA</u>	
D. Source Code (page 23)	<u>G03</u>	E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)	H. UOM (page 15) LBS
Management Method code for Source code G25		<u>W110</u>	[X] No	<u>630</u>	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg

Sec. 2	Was any of this waste managed on site? (page 24)	
[] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)		
[X] No (SKIP TO SEC 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H077</u>	D. Total quantity shipped in 2001 (page 26) <u>630</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u> </u>	D. Total quantity shipped in 2001 (page 26) <u> </u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u> </u>	D. Total quantity shipped in 2001 (page 26) <u> </u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) HYDROCHLORIC ACID				
B. EPA hazardous waste code (page 22)		C. State hazardous waste code (page 22)			
<u>D002</u>		<u>D006</u>			
<u>D007</u>		<u>NA</u>			
D. Source Code (page 23)		E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)	H. UOM (page 15) Density
<u>G02</u>					<u>LBS</u>
Management Method code for Source code G25					<input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
		<u>W103</u>	<input checked="" type="checkbox"/> No	<u>12838</u>	

Sec. 2	Was any of this waste managed on site? (page 24)	
[] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)		
[X] No (SKIP TO SEC 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>IND000646943</u>	<u>H077</u>	<u>10228</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>NA</u>		
Site 3	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>NA</u>		

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL PROTECTION AGENCY

2001 Hazardous Waste Report

FORM GM

WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) <u>IRIDITE RAGS</u>				
B. EPA hazardous waste code (page 22) <u>NA</u> <u>NA</u> <u>NA</u>			C. State hazardous waste code (page 22) <u>NA</u> <u>NA</u>		
D. Source Code (page 23) <u>G01</u> Management Method code for Source code G25		E. Form code (page 23) <u>W002</u>	F. RCRA radioactive mixed (page 23) <input checked="" type="checkbox"/> No	G. Quantity generated in 2001 (page 23) <u>167</u>	
H. UOM (page 15) <u>LBS</u> Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg					

Sec. 2	Was any of this waste managed on site? (page 24) <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)		On-site Management Method code (page 24)
Quantity treated, disposed, or recycled on site in 2001 (page 25)		Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26) <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H131</u>	D. Total quantity shipped in 2001 (page 26) <u>134</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) <u>TURCO SLUDGE</u>				
B. EPA hazardous waste code (page 22)		<u>D004</u>	<u>D006</u>	C. State hazardous waste code (page 22)	
<u>D008</u>		<u>D010</u>	<u>NA</u>	<u>NA</u> <u>NA</u>	
D. Source Code (page 23)		E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)	H. UOM (page 15) <u>LBS</u> Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg.
<u>G02</u> Management Method code for Source code G25		<u>W609</u>	<input checked="" type="checkbox"/> No	<u>199</u>	

Sec. 2	Was any of this waste managed on site? (page 24) [] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) [X] No (SKIP TO SEC 3)			
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2		
On-site Management Method code (page 24)		Quantity treated, disposed, or recycled on site in 2001 (page 25)		

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26) <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H131</u>	D. Total quantity shipped in 2001 (page 26) <u>42</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) CADMIUM SOLUTION				
	B. EPA hazardous waste code (page 22) <u>NA</u> <u>D002</u> <u>D006</u> <u>NA</u> <u>NA</u> <u>NA</u>		C. State hazardous waste code (page 22) <u>NA</u> <u>NA</u>		
	D. Source Code (page 23) <u>G03</u> Management Method code for Source code G25	E. Form code (page 23) <u>W103</u>	F. RCRA radioactive mixed (page 23) <input checked="" type="checkbox"/> No	G. Quantity generated in 2001 (page 23) <u>455</u>	H. UOM (page 15) Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg. <u>LBS</u>

Sec. 2	Was any of this waste managed on site? (page 24) <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC 3)	
	ON-SITE PROCESS SYSTEM 1 On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)	ON-SITE PROCESS SYSTEM 2 On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26) <input type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input checked="" type="checkbox"/> 2 No (FORM IS COMPLETE)			
	Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u> </u>	D. Total quantity shipped in 2001 (page 26) <u> </u>
	Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u> </u>	D. Total quantity shipped in 2001 (page 26) <u> </u>
	Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u> </u>	D. Total quantity shipped in 2001 (page 26) <u> </u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) <u>OLIVE DRAB IRIDITE</u>				
B. EPA hazardous waste code (page 22)		<u>D006</u>	<u>D007</u>	C. State hazardous waste code (page 22)	
<u>D008</u>		<u>NA</u>	<u>NA</u>	<u>NA</u> <u>NA</u>	
D. Source Code (page 23)	<u>G06</u>	E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)	H. UOM (page 15) Density
Management Method code for Source code G25		<u>W101</u>	<input checked="" type="checkbox"/> No	<u>752</u>	<u>LBS</u> <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg

Sec. 2	Was any of this waste managed on site? (page 24)	
<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H071</u>	D. Total quantity shipped in 2001 (page 26) <u>752</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) _____	D. Total quantity shipped in 2001 (page 26) _____
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) _____	D. Total quantity shipped in 2001 (page 26) _____

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

2001 Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) CADMIUM FILTERS, WET (FREE LIQUID)				
B. EPA hazardous waste code (page 22)		<u>D002</u>	<u>D006</u>	C. State hazardous waste code (page 22)	
<u>NA</u>		<u>NA</u>	<u>NA</u>	<u>NA</u>	
D. Source Code (page 23)		E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)	H. UOM (page 15) Density
<u>G16</u> Management Method code for Source code G25		<u>W519</u>	<u>[X] No</u>	<u>55</u>	<u>LBS</u> <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg

Sec. 2	Was any of this waste managed on site? (page 24)	
[] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)		
[X] No (SKIP TO SEC 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24)
		Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H131</u>	D. Total quantity shipped in 2001 (page 26) <u>55</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

2001 Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) BRIGHT DIP				
B. EPA hazardous waste code (page 22)			C. State hazardous waste code (page 22)		
<u>D002</u> <u>D006</u> <u>D007</u> <u>D008</u> <u>NA</u>			<u>NA</u> <u>NA</u>		
D. Source Code (page 23)		E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)	H. UOM (page 15) Density
<u>G06</u> Management Method code for Source code G25		<u>W103</u>	[X] No	<u>6525</u>	<u>LBS</u> <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg

Sec. 2	Was any of this waste managed on site? (page 24)	
<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>IND000646943</u>	<u>H077</u>	<u>5178</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>NA</u>		
Site 3	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>NA</u>		

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL PROTECTION AGENCY

2001 Hazardous Waste Report

FORM GM

WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) CARBON				
B. EPA hazardous waste code (page 22)		C. State hazardous waste code (page 22)			
<u>NA</u> <u>D006</u> <u>NA</u>		<u>NA</u> <u>NA</u>			
D. Source Code (page 23)		E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)	
<u>G07</u>					
Management Method code for Source code G25					
		<u>W310</u>	<input checked="" type="checkbox"/> No	<u>97</u>	
				H. UOM (page 15) Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	
				<u>LBS</u>	

Sec. 2	Was any of this waste managed on site? (page 24)	
	<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)	
	<input checked="" type="checkbox"/> No (SKIP TO SEC 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)		On-site Management Method code (page 24)
Quantity treated, disposed, or recycled on site in 2001 (page 25)		Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
	<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>IND000646943</u>	<u>H131</u>	<u>97</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>NA</u>		
Site 3	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>NA</u>		

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOTEPA ID NO: PA5213820892U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GMWASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) ZINC PHOSPHATE SLUDGE				
B. EPA hazardous waste code (page 22)		C. State hazardous waste code (page 22)			
<u>NA</u> <u>D002</u> <u>D006</u> <u>NA</u> <u>NA</u> <u>NA</u>		<u>NA</u> <u>NA</u>			
D. Source Code (page 23) <u>G02</u> Management Method code for Source code G25		E. Form code (page 23) <u>W103</u>	F. RCRA radioactive mixed (page 23) [X] No	G. Quantity generated in 2001 (page 23) <u>137</u>	H. UOM (page 15) Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg <u>LBS</u>

Sec. 2	Was any of this waste managed on site? (page 24) [] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) [X] No (SKIP TO SEC 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)		On-site Management Method code (page 24)
Quantity treated, disposed, or recycled on site in 2001 (page 25)		Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26) <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H077</u>	D. Total quantity shipped in 2001 (page 26) <u>137</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u> </u>	D. Total quantity shipped in 2001 (page 26) <u> </u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u> </u>	D. Total quantity shipped in 2001 (page 26) <u> </u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) ZINCATE (ALUMINAL)				
B. EPA hazardous waste code (page 22)		C. State hazardous waste code (page 22)			
<u>D002</u> <u>D006</u> <u>D007</u> <u>D008</u> <u>NA</u>		<u>NA</u> <u>NA</u>			
D. Source Code (page 23) <u>G06</u> Management Method code for Source code G25		E. Form code (page 23) <u>W110</u>	F. RCRA radioactive mixed (page 23) [X] No	G. Quantity generated in 2001 (page 23) <u>51</u>	H. UOM (page 15) <u>LBS</u> Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg

Sec. 2	Was any of this waste managed on site? (page 24) [] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) [X] No (SKIP TO SEC 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)		On-site Management Method code (page 24)
Quantity treated, disposed, or recycled on site in 2001 (page 25)		Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26) <input type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input checked="" type="checkbox"/> 2 No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) _____	D. Total quantity shipped in 2001 (page 26) _____
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) _____	D. Total quantity shipped in 2001 (page 26) _____
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) _____	D. Total quantity shipped in 2001 (page 26) _____

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOTEPA ID NO: PA5213820892U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GMWASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) CAD BAGS AND DEBRIS FROM CAD PLATING TANK				
	B. EPA hazardous waste code (page 22) <u>NA</u> <u>NA</u> <u>NA</u>		C. State hazardous waste code (page 22) <u>NA</u> <u>NA</u>		
	D. Source Code (page 23) <u>G19</u> Management Method code for Source code G25	E. Form code (page 23) <u>W519</u>	F. RCRA radioactive mixed (page 23) [X] No	G. Quantity generated in 2001 (page 23) <u>201</u>	H. UOM (page 15) Density <u>LBS</u> <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg.

Sec. 2	Was any of this waste managed on site? (page 24) [] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) [X] No (SKIP TO SEC 3)	
	ON-SITE PROCESS SYSTEM 1	ON-SITE PROCESS SYSTEM 2
	On-site Management Method code (page 24)	On-site Management Method code (page 24)
	Quantity treated, disposed, or recycled on site in 2001 (page 25)	Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26) <input type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input checked="" type="checkbox"/> 2 No (FORM IS COMPLETE)		
	Site 1	Site 2	Site 3
	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>
	C. Off-site Management Method code Shipped to (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u>NA</u>
	D. Total quantity shipped in 2001 (page 26) <u>NA</u>	D. Total quantity shipped in 2001 (page 26) <u>NA</u>	D. Total quantity shipped in 2001 (page 26) <u>NA</u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) <u>ALUMINUM ETCH</u>				
B. EPA hazardous waste code (page 22)		<u>D002</u>	<u>D007</u>	C. State hazardous waste code (page 22)	
<u>NA</u>		<u>NA</u>	<u>NA</u>	<u>NA</u> <u>NA</u>	
D. Source Code (page 23)	<u>G04</u>	E. Form code (page 23)	<u>W110</u>	F. RCRA radioactive mixed (page 23)	[X] No
Management Method code for Source code G25				G. Quantity generated in 2001 (page 23)	<u>1476</u>
				H. UOM (page 15) Density	<u>LBS</u> <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg

Sec. 2	Was any of this waste managed on site? (page 24)	
[] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)		
[X] No (SKIP TO SEC 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H077</u>	D. Total quantity shipped in 2001 (page 26) <u>910</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOTEPA ID NO: PA5213820892U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GMWASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) LEAK TEST WATER				
B. EPA hazardous waste code (page 22)		C. State hazardous waste code (page 22)			
<u>NA</u> <u>NA</u> <u>NA</u>		<u>NA</u> <u>NA</u>			
D. Source Code (page 23) <u>G07</u> Management Method code for Source code G25		E. Form code (page 23) <u>W101</u>	F. RCRA radioactive mixed (page 23) <input checked="" type="checkbox"/> No	G. Quantity generated in 2001 (page 23) <u>1162</u>	H. UOM (page 15) Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg. <u>LBS</u>

Sec. 2	Was any of this waste managed on site? (page 24) <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)		On-site Management Method code (page 24)
Quantity treated, disposed, or recycled on site in 2001 (page 25)		Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26) <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H071</u>	D. Total quantity shipped in 2001 (page 26) <u>1021</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) WASTE TIN SLUDGE				
	B. EPA hazardous waste code (page 22) <u>NA</u> <u>NA</u> <u>NA</u>		C. State hazardous waste code (page 22) <u>NA</u> <u>NA</u>		
	D. Source Code (page 23) <u>G03</u> Management Method code for Source code G25	E. Form code (page 23) <u>W110</u>	F. RCRA radioactive mixed (page 23) [X] No	G. Quantity generated in 2001 (page 23) <u>240</u>	H. UOM (page 15) Density <u>LBS</u> <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
Sec. 2	Was any of this waste managed on site? (page 24) [] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) [X] No (SKIP TO SEC 3)				
	ON-SITE PROCESS SYSTEM 1 On-site Management Method code (page 24)		ON-SITE PROCESS SYSTEM 2 On-site Management Method code (page 24)		
	Quantity treated, disposed, or recycled on site in 2001 (page 25)		Quantity treated, disposed, or recycled on site in 2001 (page 25)		

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26) <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
	Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H121</u>	D. Total quantity shipped in 2001 (page 26) <u>240</u>
	Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u>NA</u>	D. Total quantity shipped in 2001 (page 26) <u>NA</u>
	Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u>NA</u>	D. Total quantity shipped in 2001 (page 26) <u>NA</u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

2001 Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) WASTE DIESEL FUEL				
B. EPA hazardous waste code (page 22) <u>NA</u> <u>NA</u> <u>NA</u>			C. State hazardous waste code (page 22) <u>NA</u> <u>NA</u>		
D. Source Code (page 23) <u>G16</u> Management Method code for Source code G25		E. Form code (page 23) <u>W205</u>	F. RCRA radioactive mixed (page 23) [X] No	G. Quantity generated in 2001 (page 23) <u>617</u>	H. UOM (page 15) <u>LBS</u> Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg

Sec. 2	Was any of this waste managed on site? (page 24) [] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) [X] No (SKIP TO SEC 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)		On-site Management Method code (page 24)
Quantity treated, disposed, or recycled on site in 2001 (page 25)		Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26) <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H061</u>	D. Total quantity shipped in 2001 (page 26) <u>617</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u>NA</u>	D. Total quantity shipped in 2001 (page 26) <u>NA</u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u>NA</u>	D. Total quantity shipped in 2001 (page 26) <u>NA</u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

2001 Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) EQUIPMENT CONTAINING MERCURY				
B. EPA hazardous waste code (page 22)		<u>D009</u>	<u>NA</u>	C. State hazardous waste code (page 22)	
<u>NA</u>		<u>NA</u>	<u>NA</u>	<u>NA</u> <u>NA</u>	
D. Source Code (page 23)		<u>G15</u>	E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)
Management Method code for Source code G25			<u>W117</u>	<input checked="" type="checkbox"/> No	<u>43</u>
					H. UOM (page 15) <u>LBS</u> Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg.

Sec. 2	Was any of this waste managed on site? (page 24)	
<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H131</u>	D. Total quantity shipped in 2001 (page 26) <u>43</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

2001 Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) <u>NICAD BATTERIES - WET</u>				
B. EPA hazardous waste code (page 22)		<u>D002</u>	<u>D006</u>	C. State hazardous waste code (page 22)	
<u>NA</u>		<u>NA</u>	<u>NA</u>	<u>NA</u> <u>NA</u>	
D. Source Code (page 23)	<u>G16</u>	E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)	H. UOM (page 15) Density
Management Method code for Source code G25		<u>W309</u>	<u>[X]</u> No	<u>100</u>	<u>LBS</u> <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg

Sec. 2	Was any of this waste managed on site? (page 24)	
<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H131</u>	D. Total quantity shipped in 2001 (page 26) <u>100</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) _____	D. Total quantity shipped in 2001 (page 26) _____
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) _____	D. Total quantity shipped in 2001 (page 26) _____

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOTEPA ID NO: PA5213820892U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GMWASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) BLACK MAGIC OXIDE				
	B. EPA hazardous waste code (page 22) <u>D007</u> <u>NA</u>		D006 <u>NA</u>		C. State hazardous waste code (page 22) <u>NA</u> <u>NA</u>
	D. Source Code (page 23) <u>G06</u> Management Method code for Source code G25	E. Form code (page 23) <u>W110</u>	F. RCRA radioactive mixed (page 23) [X] No	G. Quantity generated in 2001 (page 23) <u>1329</u>	H. UOM (page 15) <u>LBS</u> Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg.

Sec. 2	Was any of this waste managed on site? (page 24) [] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) [X] No (SKIP TO SEC 3)	
	ON-SITE PROCESS SYSTEM 1 On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)	ON-SITE PROCESS SYSTEM 2 On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26) <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	Site 1	Site 2	Site 3
	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>
	C. Off-site Management Method code Shipped to (page 26) <u>H131</u>	C. Off-site Management Method code Shipped to (page 26)	C. Off-site Management Method code Shipped to (page 26)
	D. Total quantity shipped in 2001 (page 26) <u>1329</u>	D. Total quantity shipped in 2001 (page 26)	D. Total quantity shipped in 2001 (page 26)

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) <u>ALODINE RAGS</u>				
B. EPA hazardous waste code (page 22)		<u>D007</u>	<u>NA</u>	C. State hazardous waste code (page 22)	
<u>NA</u>		<u>NA</u>	<u>NA</u>	<u>NA</u>	
D. Source Code (page 23)		<u>G06</u>	E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)
Management Method code for Source code G25			<u>W519</u>	<input checked="" type="checkbox"/> No	<u>67</u>
				H. UOM (page 15) Density	<u>LBS</u>
				<input type="checkbox"/> 1 lbs/gal	<input type="checkbox"/> 2 sg.

Sec. 2	Was any of this waste managed on site? (page 24)	
	[] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)	
	<input checked="" type="checkbox"/> No (SKIP TO SEC 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24)
		Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
	<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H131</u>	D. Total quantity shipped in 2001 (page 26) <u>30</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) PLATING SHOP WOOD FLOORING				
	B. EPA hazardous waste code (page 22) <u>NA</u>		C. State hazardous waste code (page 22) <u>NA</u>		
D. Source Code (page 23) <u>G32</u> Management Method code for Source code G25	E. Form code (page 23) <u>W002</u>	F. RCRA radioactive mixed (page 23) [X] No	G. Quantity generated in 2001 (page 23) <u>174</u>	H. UOM (page 15) Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg. <u>LBS</u>	

Sec. 2	Was any of this waste managed on site? (page 24) [] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) [X] No (SKIP TO SEC 3)	
	ON-SITE PROCESS SYSTEM 1 On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)	ON-SITE PROCESS SYSTEM 2 On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26) <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	Site 1 B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H131</u>	D. Total quantity shipped in 2001 (page 26) <u>174</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) 	D. Total quantity shipped in 2001 (page 26)
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) 	D. Total quantity shipped in 2001 (page 26)

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1 A. Waste description (page 22)
POLY & DEBRIS FROM BLDG 9 BAGHOUSE CLEAN UP

B. EPA hazardous waste code (page 22)
NA D006 D007
NA NA NA

C. State hazardous waste code (page 22)
NA NA

D. Source Code (page 23)
G32
Management Method code for
Source code G25

E. Form code
(page 23)

W002

F. RCRA
radioactive
mixed
(page 23)

☒ No

G. Quantity generated in 2001 (page 23)

132

H. UOM
(page 15)
Density

LBS

☐ 1 lbs/gal ☐ 2 sg

Sec. 2 Was any of this waste managed on site? (page 24)
[] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)
[X] No (SKIP TO SEC 3)

ON-SITE PROCESS SYSTEM 1

On-site Management
Method code (page 24)

Quantity treated, disposed, or
recycled on site in 2001 (page 25)

ON-SITE PROCESS SYSTEM 2

On-site Management
Method code (page 24)

Quantity treated, disposed, or
recycled on site in 2001 (page 25)

Sec. 3 A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)
☒ 1 Yes (CONTINUE TO BOX B) ☐ 2 No (FORM IS COMPLETE)

Site 1 B. EPA ID No. of facility waste was shipped
(page 26)
IND000646943

C. Off-site Management Method code
Shipped to (page 26)

H131

D. Total quantity shipped in 2001
(page 26)

132

Site 2 B. EPA ID No. of facility waste was shipped
(page 26)
NA

C. Off-site Management Method code
Shipped to (page 26)

D. Total quantity shipped in 2001
(page 26)

Site 3 B. EPA ID No. of facility waste was shipped
(page 26)
NA

C. Off-site Management Method code
Shipped to (page 26)

D. Total quantity shipped in 2001
(page 26)

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) <u>PREWASH PART A SPILL</u>				
B. EPA hazardous waste code (page 22)		<u>D001</u>	<u>D007</u>	C. State hazardous waste code (page 22)	
<u>NA</u>		<u>NA</u>	<u>NA</u>	<u>NA</u> <u>NA</u>	
D. Source Code (page 23)		<u>G32</u>	E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)
Management Method code for Source code G25			<u>W209</u>	<u>[X]</u> No	<u>77</u>
					H. UOM (page 15) <u>LBS</u> Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg

Sec. 2	Was any of this waste managed on site? (page 24)			
[] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)				
[X] No (SKIP TO SEC 3)				
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2		
On-site Management Method code (page 24)		Quantity treated, disposed, or recycled on site in 2001 (page 25)		On-site Management Method code (page 24)
				Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>IND000646943</u>	<u>H040</u>	<u>77</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>NA</u>		
Site 3	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>NA</u>		

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOTEPA ID NO: PA5213820892U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GMWASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1 A. Waste description (page 22)
STEEL DUST SPILL CLEAN UP AND DEBRISB. EPA hazardous waste code (page 22) D006 NA
NA NA NA

C. State hazardous waste code (page 22)

NA NAD. Source Code (page 23) G32
Management Method code for
Source code G25

E. Form code (page 23)

W319F. RCRA
radioactive
mixed
(page 23)☒ No

G. Quantity generated in 2001 (page 23)

2139H. UOM (page 15) LBS
Density☐ 1 lbs/gal ☐ 2 sgSec. 2 Was any of this waste managed on site? (page 24)
☐ Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)
☒ No (SKIP TO SEC 3)

ON-SITE PROCESS SYSTEM 1

On-site Management
Method code (page 24)Quantity treated, disposed, or
recycled on site in 2001 (page 25)

ON-SITE PROCESS SYSTEM 2

On-site Management
Method code (page 24)Quantity treated, disposed, or
recycled on site in 2001 (page 25)Sec. 3 A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)
☒ 1 Yes (CONTINUE TO BOX B) ☐ 2 No (FORM IS COMPLETE)Site 1 B. EPA ID No. of facility waste was shipped (page 26)
IND000646943C. Off-site Management Method code
Shipped to (page 26)H131D. Total quantity shipped in 2001
(page 26)2139Site 2 B. EPA ID No. of facility waste was shipped (page 26)
NAC. Off-site Management Method code
Shipped to (page 26)D. Total quantity shipped in 2001
(page 26)Site 3 B. EPA ID No. of facility waste was shipped (page 26)
NAC. Off-site Management Method code
Shipped to (page 26)D. Total quantity shipped in 2001
(page 26)

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) <u>STRIPPER RAGS</u>				
B. EPA hazardous waste code (page 22)		<u>D006</u>	<u>D010</u>	C. State hazardous waste code (page 22)	
<u>NA</u>		<u>NA</u>	<u>NA</u>	<u>NA</u> <u>NA</u>	
D. Source Code (page 23)		<u>G02</u>	E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)
Management Method code for Source code G25			<u>W519</u>	<input checked="" type="checkbox"/> No	<u>342</u>
					H. UOM (page 15) <u>LBS</u> Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg.

Sec. 2	Was any of this waste managed on site? (page 24)	
[] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)		
[X] No (SKIP TO SEC 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H131</u>	D. Total quantity shipped in 2001 (page 26) <u>222</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOTEPA ID NO: PA5213820892U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GMWASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) CARBON				
B. EPA hazardous waste code (page 22)		<u>D002</u>	<u>D006</u>	C. State hazardous waste code (page 22)	
<u>NA</u>		<u>NA</u>	<u>NA</u>	<u>NA</u> <u>NA</u>	
D. Source Code (page 23)		E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)	H. UOM (page 15) Density
<u>G07</u> Management Method code for Source code G25		<u>W310</u>	[X] No	<u>136</u>	<u>LBS</u> <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg

Sec. 2	Was any of this waste managed on site? (page 24)	
[] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)		
[X] No (SKIP TO SEC 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26).		
<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>IND000646943</u>	<u>H131</u>	<u>136</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>NA</u>		
Site 3	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>NA</u>		

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) <u>MARINE RESIN, PART A</u>				
B. EPA hazardous waste code (page 22)		C. State hazardous waste code (page 22)			
<u>NA</u> <u>NA</u> <u>NA</u>		<u>NA</u> <u>NA</u>			
D. Source Code (page 23)	<u>G32</u>	E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)	H. UOM (page 15) Density
Management Method code for Source code G25		<u>W219</u>	<u>[X]</u> No	<u>74</u>	<u>LBS</u> <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg

Sec. 2	Was any of this waste managed on site? (page 24)	
<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H141</u>	D. Total quantity shipped in 2001 (page 26) <u>74</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOTEPA ID NO: PA5213820892U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GMWASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) LABPACK EXCESS AEROSOLS				
B. EPA hazardous waste code (page 22)		<u>D001</u>	<u>NA</u>	C. State hazardous waste code (page 22)	
<u>NA</u>		<u>NA</u>	<u>NA</u>	<u>NA</u> <u>NA</u>	
D. Source Code (page 23)		<u>G11</u>	E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)
Management Method code for Source code G25			<u>W001</u>	<input checked="" type="checkbox"/> No	<u>264</u>
					H. UOM (page 15) <u>LBS</u> Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg.

Sec. 2	Was any of this waste managed on site? (page 24) [] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) [X] No (SKIP TO SEC 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26) <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H040</u>	D. Total quantity shipped in 2001 (page 26) <u>264</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) EXCESS FLAMMABLE LIQUIDS				
B. EPA hazardous waste code (page 22)		<u>D001</u>	<u>NA</u>	C. State hazardous waste code (page 22)	
<u>NA</u>		<u>NA</u>	<u>NA</u>	<u>NA</u>	
D. Source Code (page 23)		<u>G11</u>	E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)
Management Method code for Source code G25			<u>W001</u>	<input checked="" type="checkbox"/> No	<u>739</u>
					H. UOM (page 15) <u>LBS</u> Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
Sec. 2	Was any of this waste managed on site? (page 24)				
[] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)					
[X] No (SKIP TO SEC 3)					
ON-SITE PROCESS SYSTEM 1			ON-SITE PROCESS SYSTEM 2		
On-site Management Method code (page 24)		Quantity treated, disposed, or recycled on site in 2001 (page 25)		On-site Management Method code (page 24)	
				Quantity treated, disposed, or recycled on site in 2001 (page 25)	

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H040</u>	D. Total quantity shipped in 2001 (page 26) <u>739</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>

Comments:

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR
ENTER:SITE NAME: TOBYHANNA ARMY DEPOTEPA ID NO: PA5213820892FORM
GMWASTE GENERATION
AND MANAGEMENTInstructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before
completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) LABPACK EXCESS FLAMMABLE LIQUIDS				
	B. EPA hazardous waste code (page 22) NA		C. State hazardous waste code (page 22) NA		
	D. Source Code (page 23) G11 Management Method code for Source code G25	E. Form code (page 23) W001	F. RCRA radioactive mixed (page 23) [X] No	G. Quantity generated in 2001 (page 23) 328	H. UOM (page 15) Density LBS <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg

Sec. 2	Was any of this waste managed on site? (page 24) [] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) [X] No (SKIP TO SEC 3)	
	ON-SITE PROCESS SYSTEM 1	ON-SITE PROCESS SYSTEM 2
	On-site Management Method code (page 24)	On-site Management Method code (page 24)
	Quantity treated, disposed, or recycled on site in 2001 (page 25)	Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26) <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	Site 1	Site 2	Site 3
	B. EPA ID No. of facility waste was shipped (page 26) IND000646943	B. EPA ID No. of facility waste was shipped (page 26) NA	B. EPA ID No. of facility waste was shipped (page 26) NA
	C. Off-site Management Method code Shipped to (page 26) H040	C. Off-site Management Method code Shipped to (page 26)	C. Off-site Management Method code Shipped to (page 26)
	D. Total quantity shipped in 2001 (page 26) 328	D. Total quantity shipped in 2001 (page 26)	D. Total quantity shipped in 2001 (page 26)

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

2001 Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) LABPACK EXCESS FLAMMABLE LIQUIDS				
B. EPA hazardous waste code (page 22)		<u>D001</u>	<u>D035</u>	C. State hazardous waste code (page 22)	
<u>U239</u>		<u>NA</u>	<u>NA</u>	<u>NA</u> <u>NA</u>	
D. Source Code (page 23)		E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)	H. UOM (page 15) Density
<u>G11</u> Management Method code for Source code G25		<u>W001</u>	<u>[X]</u> No	<u>166</u>	<u>LBS</u> <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg

Sec. 2	Was any of this waste managed on site? (page 24)	
<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>IND000646943</u>	<u>H040</u>	<u>166</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>NA</u>		
Site 3	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>NA</u>		

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOTEPA ID NO: PA5213820892U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GMWASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) LABPACK EXCESS COROSSIVE LIQUIDS				
B. EPA hazardous waste code (page 22)		C. State hazardous waste code (page 22)			
<u>NA</u> <u>NA</u> <u>NA</u>		<u>NA</u> <u>NA</u>			
D. Source Code (page 23)	E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)	H. UOM (page 15) Density	
<u>G11</u> Management Method code for Source code G25	<u>W001</u>	<input checked="" type="checkbox"/> No	<u>19</u>	<u>LBS</u> <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg.	

Sec. 2	Was any of this waste managed on site? (page 24)	
[] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)		
[X] No (SKIP TO SEC 3)		
ON-SITE PROCESS SYSTEM 1		
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	
ON-SITE PROCESS SYSTEM 2		
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H121</u>	D. Total quantity shipped in 2001 (page 26) <u>19</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) LABPACK EXCESS CORROSIVE LIQUIDS				
B. EPA hazardous waste code (page 22)		<u>D004</u>	<u>U080</u>	C. State hazardous waste code (page 22)	
<u>U226</u>		<u>NA</u>	<u>NA</u>	<u>NA</u> <u>NA</u>	
D. Source Code (page 23)	<u>G11</u>	E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)	H. UOM (page 15) Density
Management Method code for Source code G25		<u>W001</u>	<input checked="" type="checkbox"/> No	<u>64</u>	<u>LBS</u> <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg

Sec. 2	Was any of this waste managed on site? (page 24)			
<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC 3)				
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2		
On-site Management Method code (page 24)		On-site Management Method code (page 24)		Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>IND000646943</u>	C. Off-site Management Method code Shipped to (page 26) <u>H040</u>	D. Total quantity shipped in 2001 (page 26) <u>64</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

2001 Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1 A. Waste description (page 22)
LABPACK EXCESS COROSSIVE LIQUIDS

B. EPA hazardous waste code (page 22)
NA D002 NA
NA NA NA

C. State hazardous waste code (page 22)
NA NA

D. Source Code (page 23)
G11
Management Method code for
Source code G25

E. Form code (page 23)
W001

F. RCRA
radioactive
mixed
(page 23)
☒ No

G. Quantity generated in 2001 (page 23)
10

H. UOM (page 15)
Density
☐ 1 lbs/gal ☐ 2 sg.

Sec. 2 Was any of this waste managed on site? (page 24)
☐ Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)
☒ No (SKIP TO SEC 3)

ON-SITE PROCESS SYSTEM 1

On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

ON-SITE PROCESS SYSTEM 2

On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3 A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)
☐ 1 Yes (CONTINUE TO BOX B) ☒ 2 No (FORM IS COMPLETE)

Site	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
Site 1	<u>NA</u>	<u> </u>	<u> </u>
Site 2	<u>NA</u>	<u> </u>	<u> </u>
Site 3	<u>NA</u>	<u> </u>	<u> </u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

2001 Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) <u>CLEPOX 143</u>				
B. EPA hazardous waste code (page 22) <u>NA</u> <u>NA</u> <u>NA</u>			C. State hazardous waste code (page 22) <u>NA</u> <u>NA</u>		
D. Source Code (page 23) <u>G11</u> Management Method code for Source code G25		E. Form code (page 23) <u>W519</u>	F. RCRA radioactive mixed (page 23) <input checked="" type="checkbox"/> No	G. Quantity generated in 2001 (page 23) <u>96</u>	H. UOM (page 15) Density <u>LBS</u> <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg

Sec. 2	Was any of this waste managed on site? (page 24) <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26) <input type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input checked="" type="checkbox"/> 2 No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u>NA</u>	D. Total quantity shipped in 2001 (page 26) <u>NA</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u>NA</u>	D. Total quantity shipped in 2001 (page 26) <u>NA</u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u>NA</u>	D. Total quantity shipped in 2001 (page 26) <u>NA</u>

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) WASTE COPPER FILTERS				
B. EPA hazardous waste code (page 22)		C. State hazardous waste code (page 22)			
<u>NA</u>		<u>NA</u>		<u>NA</u>	
D. Source Code (page 23)		E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)	H. UOM (page 15) Density
<u>G03</u> Management Method code for Source code G25		<u>W519</u>	<input checked="" type="checkbox"/> No	<u>24</u>	<u>LBS</u> <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg

Sec. 2	Was any of this waste managed on site? (page 24)	
<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
<input type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input checked="" type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>NA</u>		
Site 2	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>NA</u>		
Site 3	B. EPA ID No. of facility waste was shipped (page 26)	C. Off-site Management Method code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	<u>NA</u>		

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

2001 Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) WASTE PAINT GUN CLEANER				
B. EPA hazardous waste code (page 22)		<u>D001</u>	<u>D018</u>	C. State hazardous waste code (page 22)	
<u>D035</u>		<u>D039</u>	<u>D040</u>	<u>NA</u> <u>NA</u>	
D. Source Code (page 23)		E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)	H. UOM (page 15) Density
<u>G06</u> Management Method code for Source code G25		<u>W211</u>	<input checked="" type="checkbox"/> No	<u>9375</u>	<u>LBS</u> <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg.

Sec. 2	Was any of this waste managed on site? (page 24)	
<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>ILD980613913</u>	C. Off-site Management Method code Shipped to (page 26) <u>H020</u>	D. Total quantity shipped in 2001 (page 26) <u>9375</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u>NA</u>	D. Total quantity shipped in 2001 (page 26) <u>NA</u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u>NA</u>	D. Total quantity shipped in 2001 (page 26) <u>NA</u>

Comments:

Sec. I, Box B, continued: F003, F005

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: TOBYHANNA ARMY DEPOT

EPA ID NO: PA5213820892

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

2001 Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste description (page 22) PARTS WASHER SOLVENT				
B. EPA hazardous waste code (page 22)		<u>D039</u>	<u>NA</u>	C. State hazardous waste code (page 22)	
<u>NA</u>		<u>NA</u>	<u>NA</u>	<u>NA</u> <u>NA</u>	
D. Source Code (page 23)		<u>G01</u>	E. Form code (page 23)	F. RCRA radioactive mixed (page 23)	G. Quantity generated in 2001 (page 23)
Management Method code for Source code G25			<u>W211</u>	<input checked="" type="checkbox"/> No	<u>2894</u>
					H. UOM (page 15) Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
					<u>LBS</u>

Sec. 2	Was any of this waste managed on site? (page 24)	
[] Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)		
[X] No (SKIP TO SEC 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code (page 24)	Quantity treated, disposed, or recycled on site in 2001 (page 25)	On-site Management Method code (page 24) Quantity treated, disposed, or recycled on site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
<input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility waste was shipped (page 26) <u>PAD980552020</u>	C. Off-site Management Method code Shipped to (page 26) <u>H020</u>	D. Total quantity shipped in 2001 (page 26) <u>2894</u>
Site 2	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>
Site 3	B. EPA ID No. of facility waste was shipped (page 26) <u>NA</u>	C. Off-site Management Method code Shipped to (page 26) <u></u>	D. Total quantity shipped in 2001 (page 26) <u></u>

Comments: